



TL-222-T

## **Trowelable Graphite Flake-Filled Vinyl Ester Lining System**

### PRODUCT DESCRIPTION

Blome TL-222-T is a high-performance, high temperature-resistant, graphite filled, trowelable vinyl ester lining system. TL-222-T utilizes carefully selected and sized graphite reinforcement which maximizes permeation resistance and physical properties. TL-222-T is used as a coating in very demanding applications where enhanced performance and resistance to hydrofluoric acid and hot alkaline chemistry is required.

## **TYPICAL USES**

Linings for steel and concrete tanks used for a wide variety chemical processing, chemical storage, and wastewater applications. TL-222-T is well suited for lining of alkaline brine tanks, alkaline oxidizer (bleach) containment, and acid fluoride process areas.

#### HANDLING CHARACTERISTICS

TL-222-T is applied by trowel method.

#### **TYPICAL PROPERTIES**

Solids by Volume >90% Tensile strength 4.000 PSI Tensile elongation 0.3 - 0.6%Bond strength to steel 1.500 - 1.750 PSI Bond strength to concrete Concrete failure Flexural strength 7.850 PSI Permeability (perm-inch) ASTM E-96 0.0002 Coefficient of Thermal Expansion 14-16 X 10<sup>-6</sup> /°F Shelf life @ 70°F 4 months Color Dark gray to black Pot life @ 70°F 30-40 minutes Tack free @ 70°F 4-6 hours Final Cure @ 70°F\* 75%; 24 hours 100%; 5 days

\*Final cure time will be shorter at higher temperatures

Primer

Primer 205

## **PACKAGING & STORAGE**

TL-222-T is a two-component material consisting of Part A (resin) and Part B (catalyst). TL-222-T is packaged in 1 gallon, 5 gallon and drum quantities. Proper storage of these materials is critical to handling characteristics and performance. Store all components in unopened containers in a dry place, at 50-75°F, out of direct sunlight, and protect from the elements. Keep away from heat and flame. 24 hours before use, narrow the storage temperature to 70-80°F to facilitate handling of the product. This product has a shelf life of 4 months when properly stored.

#### **BID SPECIFICATION GUIDE**

Use TL-222-T filled with large diameter graphite flakes as manufactured by Blome International O'Fallon Mo. Use in accordance with manufactures most currently published technical product information.

#### APPLICATION GUIDELINES

# JOB SITE ENVIRONMENTAL CONDITIONS

The temperature of the surface to be lined and the ambient air temperature must be at least 50°F while applying this product and as it cures. Monitor weather conditions and dew point. Stop the application if the temperature falls within 5°F of the dew point. Use dehumidification and/or temperature controls if necessary to meet this requirement. Always use forced ventilation while applying this material and for its entire cure cycle.

## JOB SITE STORAGE OF MATERIALS

Proper storage of these materials is critical to handling characteristics and performance. Store all components in unopened containers in a dry place, at 50-75°F, out of direct sunlight, and protect from the elements. Keep away from heat and flame. 24 hours before use, narrow the storage temperature to 70-80°F to facilitate handling of the product.

## **SURFACE PREPARATION**

Steel: steel surfaces intended for lining application must be clean and free of oil, grease, dirt, rust, mill scale, salts, other coatings, corrosion products and other deleterious substances. Welds and weld splatter must be ground smooth. Avoid skip welds. Grind all sharp projections and round all corners to a 1/8" radius. All steel to be lined must be abrasive blasted to white metal finish (NACE no. 1, SSPC SP5) with a 2-4 mil sharp anchor profile. Mask all areas that are not to be lined.

Concrete: new concrete must cure a minimum of 28 days. Concrete surfaces should be abrasive blasted to provide a sound surface with a texture like medium grit sandpaper. Surfaces must be dry. All voids, pits, rock pockets and honeycombed surfaces should be filled with Blome CP-110HB vinyl ester mortar prior to application of TL-222-T.

#### PRIMING/SURFACE REPAIR

- Mix and apply primer by brush, roller, or spray. Apply at 6-8 mils.
  Do not allow primer to puddle. Coverage rate should be 200 250 square feet per gallon. Allow primer to cure tack free before proceeding with application of TL-222-T.
- When priming concrete, it is important to apply the primer when ambient and substrate temperatures are declining. Apply enough primer to seal the surface of the concrete without creating puddles. This may require more than one coat of primer depending on the porosity of the concrete. If more than one coat is necessary, allow each coat to cure tack free before applying the next coat.
- After the last coat of primer has cured tack free, fill any voids in the concrete surface using Blome CP-110HB vinyl ester mortar and allow to cure tack free before application of TL-222-T.

#### MIXING AND APPLICATION

- Stir Part A to a smooth, uniform consistency and color using a Jiffy type mixer.
- For every gallon of Part A, add 2-3 ounces of Part B (catalyst), and mix thoroughly for 2-3 minutes.
- Be sure to scrape the sides and bottom of the mixing pail to ensure thorough mixing.
- Pot life of the mixture using 2-3 ounces of Part B per gallon of Part A will be approximately 30-40 minutes at 75°F (significantly less at elevated temperatures).
- The longer the material is in the pail after mixing, the shorter the pot-life will be...USE IMMEDIATELY.
- Apply a 40-50 mil base coat using a trowel. Before the basecoat cures, dampen a short nap roller with styrene and roll the surface of the fresh coating to orient the graphite flakes parallel to the substrate. Allow to cure tack free before applying the topcoat.
- Before applying the topcoat, closely inspect the basecoat to ensure that there are no soft, uncured spots. If there are uncured spots, remove by scrapping and solvent wiping and reapply the TL-222-T to the area to be repaired. Sand or grind down any sharp protrusions.
- Mix topcoat material just as the basecoat. Apply 40-50 mils by trowel. Spread to an even, uniform finish. Before topcoat cures, dampen a short nap roller with styrene and roll the surface of the fresh coating to orient the graphite flakes parallel to the substrate.

## **INTER-COAT PREP**

When applying subsequent coats, allow previous coat to cure firm
to the touch. If surface is not contaminated and has not cured
beyond 72 hours at an average temperature of 75°F, no inter-coat
prep is required. If surface has been exposed to contamination or
has cured beyond 72 hours or has been exposed to direct sunlight
for over 6 hours do the following: Remove any contamination and
mechanically abrade by sanding or lightly abrasive blasting the
surface to be coated. Remove dust

### **INSPECTING FOR PINHOLES**

 TL-222-T contains conductive flake. Therefore, this lining cannot be spark tested.

#### TOUCH-UP OR RECOATING

 Allow material to cure firm to the touch. If surface is not contaminated and has not cured beyond 72 hours at an average temperature of 75°F, no inter-coat prep is required. If surface has been exposed to contamination or has cured beyond 72 hours or has been exposed to direct sunlight for over 6 hours do the following: Remove any contamination and mechanically abrade. Apply lining material and allow to cure.

#### OPTIONAL GEL-COAT

 For some applications, TL-222-S with PGC additive (aka "VEPGC"), an optional 5-10 mil gelcoat, can be applied over the lining. This will produce a smooth lining surface. A surface coated with the gel-coat will be easier to clean. Additionally, it can serve as a bond breaker between Blome TL-222-T and Blome vinyl ester mortars, including CP-110 HB. This allows for additional movement between the substrate-membrane and bed joint-membrane interfaces without compromising the integrity of the brick-membrane system. Apply gelcoat using a medium nap roller. Allow to cure 24 hours before placing in service.

#### **CURE TIME**

\*Less time required at higher temperatures

#### **CLEANUP**

Clean tools and equipment with nonflammable chlorinated solvents before material begins to set.

#### SAFETY PRECAUTIONS

The various components of TL-222-T products present health and safety hazards if they are handled improperly. Do not store, mix or use near open flame, sparks or heat source. Keep all containers closed when not in use. Always wear safety glasses, proper respirator, and protective clothing and rubber gloves while mixing or applying these products. Refer to Safety Data Sheet prior to using these products.

#### **WARRANTY**

We warrant that our goods will conform to the description contained in the order and that we have good title to all goods sold. Our material data sheets and other literature are to be considered accurate and reliable, but are used as guides only. WE GIVE NO WARRANTY OR GUARANTEE, WHETHER OF MERCHANT ABILITY OR FITNESS OF PURPOSE OR OTHERWISE, AND WE ASSUME NO LIABILITY IN CONNECTION THEREWITH. We are happy to give suggestions for applications; however, the user assumes all risks and liabilities in connection therewith regardless of any suggestion, we may give. We assume no liability for consequential or incidental damages. Our liability, in law and equity, shall be expressly limited to the replacement of non-conforming goods at our factory, or at our sole option, to repayment of the purchase price of the non-conforming goods.

Revised: July 19, 2022