

# For Immediate Release...

## Blome International Solves Recirc Water Piping Problems!

### **BLOME INTERNATIONAL** **VERSI LINE**<sup>TM</sup> FGD Structural Wrap

- High Strength
- Low Weight
- Corrosion Resistant
- Zero VOC
- Very Low Odor
- Economical

Blome International is pleased to announce a long term structural solution for deteriorating Large Diameter Recirculation Piping.

**Blome International**, a leading supplier to the Power Industry for over 30 years has developed a long term, cost effective solution to deteriorating or failing underground circulation piping. When reinforcing wires within concrete pipes corrode, “blowouts” occur which cause an unscheduled outage costing millions of dollars.

**Blome International** provides engineering support, product, and installation of proprietary carbon fiber fabric and polymer bonding agents which are specifically engineered to meet the structural requirements of your situation. An on-site assessment along with engineered repair criteria, make the carbon fiber option the most economical, *applied in place*, alternative available today. Blome has assembled the foremost experts in the industry to solve your toughest structural and deterioration issues.

Whether your piping is PCCP, or Steel, Blome can provide the tools to eliminate your problems. When fast turnaround and proven results are required, engineers turn to Blome International for their structural rehabilitation needs.

